

Title:	Beeper not Working			ID:
				0337
Date in:	Response:	Model:	Author:	
2014-10-06	2014-10-06	STX110	CMA	

Q:

The buzzer on the STX110 HRSA, S/N 6105 seems to not functioning.

A:

This could be the 1700-flag. Please do "RD 1700", if '1' then do "RS 1700"