

Title:	Speed max. Value	ID:	
		0325	
Date in:	Response:	Model:	Author:
2007-03-29	2007-03-29	-	RKi

Q:

Just as a precaution, is it possible to get a diagram or a description of where the "in" and "out" connections of each solenoid should be soldered?

A:

The solenoids are located and connected to the system like shown on the pictures below.



